

### **ABSTRACT**

While manufacturing a panel assembly including inner and outer panels through a hemming process, part of the inner panel is compressed to the outer panel and an edge of the inner panel is hemmed with a flange portion of the outer panel such that a gap is formed therebetween.

5